z:\j04-JBCC\j0401-Drain study\DWG\DESIGN\BASE.dwg, PRINTED BY: alext ON Mon, May 06 2019



LEGEND:

WCS11 STRUCTURE DESIGNATION TAG

BASIN BOUNDARY

GOLF COURSE PROPERTY

STRUCTURES NOT ACCESSED		
3-56	manhole	rusted shut
3-81	manhole	buried under sod
78-3	manhole	buried under sod
78-25	manhole	buried under sod
78-107	manhole	buried under palms
78-121	manhole	under driveway pavers; monitor this system and access if necessary
78-122	manhole	buried in sod
78-141	manhole	could not open; cover rusted in place
78-156	manhole	could not open; cover rusted in place
910-54	manhole	buried under sod
STRUCTURES NOT FOUND		
1a-1a	manhole	not installed or under pavers
1a-9a	valley with 4' box	not installed
1a-26	e inlet	spent an hour looking/probing
2-15a	e inlet	searched/probed for an hour/possibly buried in landscaping or not installed
2-15b	e inlet	searched/probed for an hour/possibly buried in landscaping or not installed
78-131	manhole	spent an hour looking/believed to be in homeowners landscaping
910-24	manhole	spent hour looking/probing
wcs43	wetland structure w/cmp	spent an hour looking/could not locate

THE MILCOR GROUP, INC.
CIVIL ENGINEERS
10975 SE FEDERAL HIGHWAY
HOBE SOUND, FL 33455

PH: (772)223-8850
FAX: (772) 223-8851
WWW.THEMILCORGROUP.COM
CERTIFICATE OF AUTHORIZATION: 28246

500 0 500 1000
(IN FEET)
1 inch = 250 ft.

NOT FOUND OR NOT ACCESSIBLE STRUCTURES

JENSEN BEACH COUNTRY CLUB